



Photo 1 – Longway Farm, 91 Janes Rd., Swanton, VT – 06/23/16
New concrete curbing around the heifer barnyard.



Photo 2 – Longway Farm, 91 Janes Rd., Swanton, VT – 06/23/16
Heavy use area outside the main barn where a new concrete pad will be installed.



Photo 3 – Longway Farm, 91 Janes Rd., Swanton, VT – 06/23/16
Clogged low-flow pipe at silage collection system, runoff entering the high-flow treatment area.



Photo 4 – Longway Farm, 91 Janes Rd., Swanton, VT – 06/23/16
View of the high-flow vegetated treatment area at the main farm.



Photo 5 – Brodeur Farm, 123 Comstock Rd., Swanton, VT – 06/23/16

Spoiled feed pile near the silage collection system; build-up of solids at the intake screen.